




# TRT International, LTD.

250 Port Street, Newark, NJ 07114, USA

Tel: 1-973-344-7100 • Fax: 1-973-344-7757 • www.usatrt.com



CUSTOMER NAME:

DATE: 10-11-15

TIME:

RECEIVED BY: Stanik


LOT#	MAKE	Range Rover	MODEL	HSE
	VIN#	SALGS2VF7FA241132		
	COLOR	Black	MFC DATE	06.15
			GVWR	6724

IM	
SP	✓

INDICATE DAMAGED AREA(S) AND MISSING ITEMS

Dirty car

d-DENT  
D-DAMAGE  
S-SCRATCH  
M-MISSING  
BR-BROKEN  
R-RUSTED



OPTIONS	Y	N	OPTIONS	Y	N	OPTIONS	PCS
ASHTRAYS		✓	ANTENNA	✓		FLOOR MATS	4
LIGHTER		✓	SPARE TIRE	✓		KEYS	2
RADIO	✓		WIPER BLADES	✓		KEY REMOTE	2
CD CHANGER	✓		TOOLS KITS	✓		HUB CUPS	1
DVD PLAYER	✓		LUG WRENCH	✓		RIMS   ALLOY RIMS <input checked="" type="checkbox"/> STEEL RIMS <input type="checkbox"/>	4
NAVIGATION	✓		SIDE MIRROR	✓		DVD REMOTE	1
TV SCREEN	✓	✓	REAR MIRROR	✓		HEADPHONES	1
CARGO COVER	✓		AIR COMPRESSOR	✓		HEAD RESTS	5
SHIFT KNOB	✓		MANUAL BOOK	✓		TITLE AT THE TIME OF RECEIVING	YES NO

RECEIVING NOTES:

oto

RECEIVING CONDITION: NIGHT TIME ☐ RAINING ☐ SNOWING ☐ CAR CONDITION: DIRTY ☐

TRT International, Ltd reserves the right to deny damage claims to any vehicles that have been accepted under one/any of the receiving and/or car conditions indicated above. TRT International, LTD will not be liable for losses arising from Flood, Earthquake, Wind, Sleet or Hail.